

2022 Community Bond Referendum

Wantagh

Union Free School District

Board of Education

Anthony Greco, Board President
Laura Reich, Vice President
Tara Cassidy, Trustee
Adam Fisher, Trustee
Kera McLaughlin, Trustee

Administration

John McNamara, Superintendent of Schools

Anthony J. Cedrone, Assistant Superintendent for Business

Tom Fucci, Director of Facilities

Architect

Mark Design Studios Architecture, PC

Construction Manager

Advanced Construction Group



Capital Projects

Bond Committee Observations Overview

Average age of school buildings is over 65 years old. Most systems met code at the time of installation, but **do not meet current code**, including ventilation and energy efficiency.

Aging infrastructure: Original Mechanical, Electrical, and Plumbing systems, deteriorating masonry, some roofing and interior ceilings/lighting. Existing HVAC systems were somewhat adequate pre-pandemic but do not address current concerns related to **health & wellness** (mechanical ventilation for fresh air to classrooms) and **safety & security.** Buildings are well maintained but key systems are beyond their useful life and in need of being corrected and improved.

General needs include site and stormwater drainage improvements, traffic safety, parking and paving.

Each school could also improve educational programs and opportunities with improvements to key spaces to better serve the curriculum and benefit the students.







Existing exterior wall panel system is deteriorated, inefficient and cannot support hurricane rated windows.



Asphalt is extensively cracked and failing with multiple areas of settlement.



2022 Community Bond Referendum





Deteriorated steel lintels, brick ties & mortar joints with brick displacement and cracking





Forest Lake Elementary School



Erosion at east fence line at Mandalay



2022 Community Bond Referendum













Deteriorated exterior doors

Deteriorated exposed steel columns & beams



2022 Community Bond Referendum





&

Forest Lake Elementary School

Existing interior windows provided limited daylight and minimal fresh air.



Many windows have failed and condensation is forming within the glazing













Interior ceilings and lighting in need of replacement



Original unit ventilators do not provide adequate ventilation or air filtration







Slate roofing is decayed and in need of replacement









Brick cracking from water infiltration and steel expansion



Steel lintels above grilles must be replaced and masonry restored







Electrical service is undersized and switchgear cabinet is decayed and rusting



Main entrance wood columns and pediment require restoration







Original wood windows in need of restoration or replacement



Aluminum windows and transom panels are failing and no longer efficient



2022 Community Bond Referendum





Original unit ventilators do not provide adequate ventilation or air filtration



Interior ceilings and lighting in need of replacement







Wantagh Middle School

Curtainwall system is decaying and failing along with operable windows within the system



Additional view of curtainwall with missing fascia, deteriorated brick control joint, rusting panels







Wantagh Middle School

Failing and deteriorated windows in window wall system



Masonry in need of restoration, including control joint, brick cracking and sealing to stop water infiltration








Wantagh Middle School

Original unit ventilators do not provide adequate ventilation or air filtration



Corridor ceilings are in need of replacement along with replacement of lighting to LED



2022 Community Bond Referendum





Brick cracking from water infiltration and steel expansion with outward displacement



Failing windows with deteriorated flashing and deflected lintel in need of replacement







Close view of failed lintel that no longer supports masonry above the opening



Deteriorated & spalled masonry brick due to water infiltration to be replaced



2022 Community Bond Referendum





Deterioration from water infiltration into masonry wall at courtyard



District auditorium in need of renovation, including replacement of original seats, flooring, lighting & sound systems and acoustic treatments



2022 Community Bond Referendum





Serving Line and Cafeterias in need of improvement for ADA compliance and efficiency



Corridor ceilings are in need of replacement along with replacement of lighting to LED





OPTION 3 LAYO

ATHLETIC RELL IMPROVEMENT

MARRIORS

Wantagh UFSD

Possible Athletic Field improvements at Wantagh High School Soccer * Baseball * Softball * Parking * Access Driveway * Toilets



Forest Lake



Possible Athletic Field improvements at Forest Lake Elementary School 2 Soccer Fields * Tennis Courts * Little League * Toilets



